## Cynthia Baran, 12:49 PM 8/18/2004, Lunch report from Eagle Gas

To: cynthia.baran@state.ma.us (Cynthia Baran)

From: "James J. Decoulos" <jamesj@decoulos.com>

Subject: Lunch report from Eagle Gas

Cc: Bcc:

Attached: C:\Photos\2004\081804\South Meadow Outfall Pipe 081704.jpg; C:\Photos\2004\081804\South Meadow Outfall Int 081704.jpg; C:\Photos\2004\081804\Eagle

ERW-4 Install.jpg; C:\Photos\2004\081804\Eagle ERW-4 Detail.jpg;

## Cynthia,

Attached are two pictures from yesterday of the South Meadow Brook outfall and the interior of the outfall pipe. Also attached are two pictures from this morning of the installation of the fourth 4 inch well, ERW-4.

The first 4 inch well from yesterday, ERW-1, had no product this morning. ERW-2 had 0.23 feet of product. I will obtain product depths of ERW-3 and ERW-4 before I leave today.

We have created a "Z" pattern with the four 4 inch wells. The photo entitled "Eagle ERW-4 Install.jpg" provides a perspective on their locations. ERW-1 is located in front of the truck on the left and ERW-3 is located on the right.

Jim

James J. Decoulos, PE, LSP Decoulos & Company 3 Electronics Avenue Danvers, MA 01923 web: www.decoulos.com

tel: 617-489-7795 fax: 877-842-9629